


## RWSM - Wrap-Around/Zipper Tube

RWSM Zipper Tube is a Cross-Linked Polyolefin Heatshrink 'Tube' which is folded around the cable, zipped up with a stainless steel channel and then shrunk.

- Cable repair without cutting the cable
- Ideal for in situ field installation
- Jointing in tight areas
- Re-entering a joint with minimal disruption, unlike epoxy joint
- 100% waterproof and low water absorption

Installation recommendations are virtually the same as for SMDW. When applying heat, check that carbonisation or crazing does not occur and do not apply heat directly onto the stainless steel channel. When shrinkage has been completed, the stippled effect on the tube surface will not be noticeable since thermochromic paint has changed colour.




Catalogue No.	Pre Shrink (mm)	After Shrink (mm)	After Shrink (mm)	Std Lengths (m)
RWSM36/10TK	38	9	2.4	1
RWSM55/13TK	57	13	2.5	1
RWSM85/20TK	85	20	3.0	1
RWSM108/27TK	110	27	3.0	1
RWSM136/30TK	138	30	3.2	1


### Technical Data

Conformant Standards Material  
 Continuous Operating Temp  
 Tensile Strength  
 Elongation at Break Point  
 Longitudinal Shrinkage  
 Breakdown Voltage  
 Volume Resistivity  
 Water Absorption  
 Flammability  
 UV Resistance

IEC; VDE; DIN  
 Cross-linked polyolefin with hot melt adhesive lining & stainless steel channel  
 -40°C to +65°C  
 17 MPa (excluding channel)  
 350% (excluding channel)  
 10%  
 12 kV/mm wall thickness  
 1.0 x 10<sup>12</sup> ohm cm/min  
 0.5% max  
 Do not use in flame prone areas  
 Passed - ISO 1408



For cable repairs For the protection of cable joints For corrosion protection




## CEC - Heatshrink End Caps

CABRICAL's End Caps are used for sealing cable ends during installation or storage. They are made from cross-linked polyolefin and have a hot melt glue liner that bonds the cap to the cable jacket.

- Quick reliable seal of cable ends
- Watertight and unlimited storage life
- Highly resistant to ultraviolet rays, aggressive soils, chemicals and corrosion

The CEC cap should be shrunk onto the cable end starting the shrinkage process from the closed end. Once shrink is complete glue should extrude from the edges of the cap.



Catalogue No.	Pre Shrink (mm)	After Shrink (mm)	Cable Range O.D. (mm)	Recovered Wall Thickness W (mm)	Length L (mm)
CEC25/8	25	8.5	10-20	2.8	68
CEC40/16	40	16.0	18-32	3.3	83
CEC55/26	55	26.0	28-48	3.5	103
CEC75/36	75	36.0	45-68	4.0	120
CEC100/52	100	52.0	55-90	4.0	140
CEC120/60	120	60.0	65-110	4.0	150

Smaller and Larger Sizes Available on Request

### Technical Data

Conformant Standards Material  
 Continuous Operating Temp  
 Shrinkage Temp (min)  
 Tensile Strength  
 Elongation at Break Point  
 Longitudinal Shrinkage  
 Dielectric Strength  
 Volume Resistivity  
 Flammability  
 UV Resistance

IEC: ASTM  
 Cross-linked polyolefin with thermoplastic mastic sealant  
 -55°C to +110°C  
 120°C  
 12 MPa  
 > 400%  
 10%  
 > 15 kV/mm wall thickness  
 1.0 x 10<sup>14</sup> ohms cm  
 Do not use in flame prone areas  
 Good

## Heatshrink Tubing Selection

These charts below are useful for selection of heatshrink. The 'lay flat' dimension of heatshrink is commonly used with large diameter heatshrink tubes, where the heatshrink is measured flattened out, and the flat dimension measured. The table below is used to convert this into a diameter as used by CABRICAL.

The bus bar table is useful to work out heatshrink requirements for bus bars. It is important to allow for bends, and use one size up if the bar has many bends. This makes it easier to get the heatshrink onto the bar.

### Bus Bars Heatshrink Selection

Bus Bar Recommended Heatshrink for Bus Bar Width (mm)	12	19	25	38	51	76	102	125	152
3.2	XLP13	XLP20	XLP25	XLP38	XLP51	XLP76	XLP102	XLP102	XLP125
4.8	XLP13	XLP20	XLP25	XLP38	XLP51	XLP76	XLP102	XLP102	XLP125
6.4		XLP20	XLP25	XLP38	XLP51	XLP76	XLP102	XLP102	XLP125
9.5				XLP38	XLP51	XLP76	XLP102	XLP102	XLP125
12.7					XLP51	XLP76	XLP102	XLP102	XLP125

Note: If bar has bends you may have to use a larger diameter heatshrink.

### Metric vs. Imperial

Metric (mm)	Imperial (inch)
1.6	1/16
3.2	1/8
4.8	3/16
6.4	1/4
8.0	5/16
9.5	3/8
12.7	1/2


### Lay Flat To Circular

Internal Diameter (mm)	Lay Flat (mm)
5	8
7	11
10	16
13	20
16	25
20	31
25	39
32	50
38	60
51	80
76	120
102	160
125	196

## Joint Failure - Most Common Causes


### Heatshrink Joint Failure

**Unequal Heating** - The most common failure of a heatshrink joint is caused by shrinking tube from one side only. The glue in glue lined heatshrink is heat activated, and is designed to melt at a point below the shrinkage point for the tubing. It is possible to shrink a tube on to a cable jacket without applying heat right around the joint.



### Heating the Rear of a Joint

The best way to heat the rear of a joint, if you can not get access to it, is to use a heat deflector. This can simply be a curved piece of tin plate. This deflects the heat around the rear of the joint and makes the heatshrink shrink all around the joint.



When shrinking heatshrink in confined spaces, or where you cannot apply heat directly to the rear of the joint, use a heat deflector with your heatgun or soft yellow flame, to heat the rear of the joint.


**Unprepared Cable Jacket** - It is essential that the cable jacket is clean and grease free, and has been roughened. Ensure the following steps are taken:

- Roughen the outer jacket of the cable for a distance of approximately five cable diameters at each end with coarse sand paper, typically 60 to 80 grit, or a fine rasp.
- Clean the roughened area with an alcohol wipe, or methylated spirits and a clean rag.
- Warm the joint area before you start the shrinkage process. This drives off any moisture, and if using a flame, flame wipe the joint area, as this creates an oxide layer for better adhesion.

**Over Heating** - If using a flame, use a soft yellow flame and move it the whole time. Do not hold on one spot. If the heatshrink becomes a chalky grey colour and texture, it has been over heated.

### Cast Resin Joints

**Heatshrink and Resin** - The most common failure of resin joints is caused by the combination of heatshrink and resin. What happens is the person creates a joint, and shrinks individual heatshrink tubes on each internal wire, and then shrinks a heatshrink sheath, non glue lined over all the wires. (Alternatively they tape the wires in a bundle.) They then seal this into a resin joint, leaving the end of the heatshrink tube outside the joint. This, in effect, creates a moisture path to the centre of the joint from outside. The essence of a resin joint is to splay the wires and connections, with minimal to no insulation, and encapsulate these in resin. Best practice is to leave the individual conductors bare and "birdcage" them which creates a total moisture block from water travelling down the conductor.




Failure mode caused by creating a moisture path into the joint

### Resin and Moisture, Cold or Mixing

**Cold** - Resins do not cure rapidly in temperatures below 20°C. Either raise the ambient temperature or warm the joint, or use the following procedure.

- Thermally insulate the joint shell using cloth or newspaper and warm if possible. Warming the cable is easiest.
  - Mix the resin rapidly, and wait a short while until you feel the heat being generated by the resin hardening process, generally a few minutes maximum.
- Moisture** - Resins do not like water, and you must ensure that all mixing equipment and moulds are moisture free. If not, the resins can foam, particularly if water is mixed into the resin. Often failure occurs after time because the resin is porous.
- Mixing** - Resins need lots of mixing. Do not combine the ingredients and give them a quick swirl, they must be thoroughly mixed.



# Heatshrink

0861 22 22 28  
 Tel: 011 608 2897/1914  
 Fax: 011 608 2900  
 E Fax: 086 657 5833  
 www.cabacelectrical.co.za  
 sales@cabacelectrical.co.za

5 Galaxy Avenue, Unit B17  
 Linbro Business Park, Linbro Park  
 Sandton



